
## LRA WATERCOURSE REPORT DATED 19th AUGUST 2014



AREA REF	LENGTH OF RIVER	LOCATION/PHOTO REF	DETAILS	SOURCE AND DATE	ACTION	LRA COMMENTS
А	RIVER WEY NAVIGATION - UNSTEAD LOCK to BROADWATER	A1: Unstead Lock, 75m downstream	2x trees fallen into river, lying parallel to offside bank. Easily passable.	NT ("On Board" update No 11 April 2014)	REPAIRED	REPAIRED
		A2: Unstead Lock, immediately upstream for 200m	repairs and strengthening works to perched embankment.	NT ("On Board" update No 11 April 2014)		REPAIRED
	RIVER WEY NAVIGATION - BROADWATER TO TROWERS BRIDGE	<b>B1:</b> Area of Broadwater Stream (towpath side) (SEE PHOTO)	sandbar formed by water issuing from stream; flags in situ to denote sandbar.	NT ("On Board" update No 11 April 2014)	SUBSTANTIALLY REPROFILED & REDUCED BUT NOT REMOVED	Sandbar close to the weir has not been removed, though it is marked as a
В		B2: Area of Broadwater Stream	2x alders leaning from offside bank. Landowner contacted and arrangements made to remove	NT ("On Board" update No 11 April 2014)	TREES CUT BACK TO WIDEN NAVIGATION CHANNEL	hazard to navigation. (5/5/14)  REPAIRED
		<b>B3</b> : drainage stream from Broadwater where it joins the navigation.(SEE PHOTO)	Van Wheel in drainage stream	LRA	The van wheel remains in the drainage stream from Broadwater where it joins the navigation.	ACTION REQUIRED
С	RIVER WEY NAVIGATION - TROWERS BRIDGE TO CATTESHALL ROAD	C1: Upstream of bridge	debris held on the upstream side of the bridge.	NT ("On Board" update No 11 April 2014)	REMOVED.	REMOVED.

D	CATTECHALLLOCK TO	<b>D1</b> : Landings weir channel junction, 10m upstream	fallen tree in river, lying to offside bank.	NT ("On Board" update No 11 April 2014)	NT say easily passable -no action-	ACTION REQUIRED TO PREVENT BLOCKAGES
		D2: Catteshall Lock, 25m upstream	damage to towpath and bank.	NT ("On Board" update No 11 April 2014)	REPAIRED	REPAIRED
E	RIVER WEY NAVIGATION - GODALMING WHARF TO TOWN BRIDGE					NO REPORTS
F		F1: Borough road bridge adjacent to Parsons Brinkerhof (SEE PHOTO)	Tree debris under Bridge	LRA		ACTION REQUIRED
G	RIVER WEY - UPSTREAM OF WESTBROOK MILL	G1:150m upstream from Mill ,south bank (SFF PHOTO)	Tree branches in water	LRA		ACTION REQUIRED
		<b>G2</b> :	Tree branches in water 250m upstream from Mill north bank ( Wey )	LRA		ACTION REQUIRED
		G3:	5 further blockages, 2 very heavy with piled up logs	LRA		ACTION REQUIRED
Н	HELL DITCH - TROWERS BRIDGE TO CATTESHALL RD	H1:	Tree down in River causing blockage	LRA		ACTION REQUIRED
J	HELL DITCH - CATTESHALL RD TO TOWN BRIDGE	J1:(SEE PHOTO)	Minor blockages Hell Ditch approx 15m upstream from road	LRA	No action since 140525	ACTION REQUIRED
		J2: (SEE PHOTO)	Still partially blocked by willow tree 11/0814 which has since grown larger!!	LRA		
K	HELL DITCH - TOWN BRIDGE TO WESTBROOK MILL	K1:	Major blockage to Hell Ditch adjacent to far weir	LRA		ACTION REQUIRED
L	HELL DITCH - UPSTREAM OF WESTBROOK MILL	L1:				NO REPORTS

